

SAS Superstructure

Location: 04-SF-80-13.2 / 13.9 Client Name: CalTrans **Run date** 22-Nov-14 **Time** 3:39 AM

04-0120F4

04-SF-80-13.2/13.9

Self-Anchored

Suspension Bridge

Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 014 Const Calendar Day: 970 Date: 05-May-2012 Saturday Inspector Name: Woo, Laraine Title: Transportation Engineer

Inspection Type: Continuous

Shift Hours: 07:00 AM 03:30 PM **Break:** 00:30 **Over Time:** 08:00

Federal ID: Location:

Reviewer: Granados, Roman Approved Date: Status: Submit

Weather

Temperature 7 AM 12 PM 4PM

Precipitation Condition Sunny, mild, light wind

Working Day 🗸 If no, explain:

Diary: Dispute

Cable Band

May 5, 2012

Weather - clear, mild, light wind

ABF Work Shift - 0700 - 1530 (8 hours)

Location: South Side Span

Compactor: No. 4 Measurements:

Strap No. 10-2 True Height 780True Width800

(Compacted 5/4)Rotated Height 783Rotated Width796

Circumference 2490

(2 cross wires - down station, 1 outboard, 1 inboard)

Strap No. 10-3 True Height 782True Width800

Rotated Height 783Rotated Width798

Circumference 2494

(7 cross wires – down station, 1 outboard, 3 inboard, 3 bottom)

Strap No. 10-4 True Height 782True Width794

Rotated Height 784Rotated Width792

Circumference 2495

Strap No. 10-5 True Height 785True Width793

Rotated Height 785Rotated Width792

Circumference 2497

Strap No. 8-1True Height 782True Width795

(Cable Band)Rotated Height 784Rotated Width787

Circumference 2486

Strap No. 8-2True Height 780True Width795

(Cable Band)Rotated Height 784Rotated Width791

Circumference 2482

(3 cross wires – up station, 1 outboard, 2 bottom)



Page 1 of 2

Daily Diary Report by Bid Item

Job Name: 04-0120F4 Inspector Name Woo, Laraine Diary #: 014 Date: 05-May-2012 Saturday

Strap No. 8-3 True Height 781True Width795 (Cable Band)Rotated Height 784Rotated Width790 Circumference 2484

Strap No. 8-4 compacted, not measured

Strap No. 8-5 compacted, straps not finished

Approximate distance covered this shift: 7.5 meters
Start strap no. 10-2 (compacted on 5/4 but not measured)
End strap no. 8-5 (compacted, one strap installed, one strap to be installed)

Miscellaneous

Ironworkers slowed down on production to avoid pinching wires. The platforms attached to the compactor were removed because of low clearance to the catwalk. 10 feet of cable remained to be finished by the end of work shift.

Labor(8 hours)

Christopher Biskner - Henry Hernandez, Stanley Dalie, Mathew Cochran, Ronny Chamberlain.

Laraine's OT – 9 hours (Shift 0700 to 1630), Saturday

04-0120F4	Bid Item:	067	C-PWS-116.067	Install & Adjust PWS 116-120
AMERICAN BRI	DGE/FLUOR, /	A JV		
04-0120F4	Bid Item:	067	C-PWS-SUC.067	Compact Suspension Cables
AMERICAN BRI				

